

EXECUTIVE SUMMARY REPORT

Van Matre Encompass Health – Rockford Refresh

June 12th, 2020

What's New?

Good morning and welcome to our executive summary report! We are currently in our second phase onsite, but due to the lower census currently, we were able to take a few extra patient rooms. We currently have drywall completed, tile started, MEP rough-ins completed, painting of the halls completed, and wall protection started!

Coming Up in the Week Ahead:

- Wall Protection
- Floor Removal
- Casework Installed
- Floor & Wall Tile



Did you know?

METAL STUDS! The interior walls of the facility are made up of metal studs, and any new walls will also be composed of them. Metal studs are c-shaped steel rods composed of a section known as the web and 2 lipped flanges on either side of and at a right angle to the web. There are openings called knockouts at regular intervals along the stud for the wiring to be run through. Metal studs differ from wood studs in that they do not warp, expand or shrink with changing temperatures, or twist. They are perfectly straight and easily stored for long periods without risk of damaging their structural integrity.

Questions? Contact: Project Manager, Peter Schmeling – 815.262.7317, PeterS@SchmelingConstruction.com
Superintendent, Kyle Lundberg– 815.298.1031, KyleL@SchmelingConstruction.com

SCHMELING CONSTRUCTION CO.
Schmeling
BUILDING ON PRINCIPLES
SINCE 1903